












ASSEMBLY INSTRUCTIONS
















ITEM NO.:92433/92436




PARTS IDENTIFICATION


A		Left	1pc		E		1pc
B		Right	1pc		F		3pcs
C			1pc		G		Long 2pcs
D			6pcs		H		Short 2pcs
					I		1pc
					J		1pc

HARDWARE LIST


1 M6x10  4pcs	2 M6x20  4pcs	3 M6x35  4pcs
4 M6x45  16pcs	5 4x4  1pc	6 M6x16  8pcs
7 M4x15  2pcs	8  1pc	9  2pcs
10 M5x12  8pcs	11 M5x30  24pcs	12 M4x37  1pc
13  2pcs	14  1pc	15  1pc





PARTS IDENTIFICATION






STEP 1.






3		4pcs
M6x35		
4		12pcs
M6x45		




STEP 2.





10		8pcs
M5x12		
11		24pcs
M5x30		

STEP 3.







1		4pcs
M6x10		
2		4pcs
M6x20		
13		1pc

STEP 4.






SCREWDRIVER
(NOT PROVIDED)






6		8pcs
M6x16		
7		2pcs
M4x15		
9		2pcs

STEP 5.




4		4pcs
M6x45		




STEP 6.




STEP 7.






STEP 8.




STEP 9.




12		1pc
M4x37		
13		1pc
14		1pc

STEP 10.



To Prevent Tip over
Product Must Be
Attached To Wall



15		1pc
----	---	-----